Test Report

Report No.：NAP2510008601EC

Applicant: Hangzhou Tiger Electron& Electric Co.,Ltd.

Address: No.15 Xingfa Rd., Xingqiao Town, Linping District, Hangzhou,P.R. China

The following test sample information is provided and confirmed by the applicant:

Sample Name:	LED lamp
Model:	C37-9W-B, TS22BM-3CCT-7W
Additional model:	Please see page 2 below
Remark:	"-A"=3W,4W,5W...200W,represent product power, "-B"=2700K,3000K,3500K....10000K,represent the color temperature of the product "-C"=E12,E14,E27,E40,E26,B22, Represent different lamp heads

Date of sample(s) received：	Oct.10,2025
Date of Test Period：	Oct.10,2025 ~ Oct.21,2025
Date of Report：	Jun.29,2026

TEST REQUESTED	**CONCLUSION**
1. As specified by client, to determine the EU RoHS Directive 2011/65/EU Annex II and amending Directive (EU) 2015/863 substance content in the submitted sample.	PASS

NAP Testing Technology Service(Zhongshan) Co., LTD

Lian Yi

Authorized Signatory

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.

NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

The following test sample information is provided and confirmed by the applicant:

Additional model: C37-A-B-C, C37L-A-B-C, G45-A-B-C, GU5 .3-A-B, GU5 .3-A-B-38℃, GU5 .3-3CCT-38° C, GU10-A-B, GU10-A-B-38° , GU10-3CCT-38° C, GU10 DIM-A-B-38° , A55-A-B-C, A60-A-B-C, A65-A-B-C, A70-A-B-C, A80-A-B-C, A95-A-B-C, A110-A-B-C, T50-A-B-C, T60-A-B-C, T70-A-B-C, T80-A-B-C, T100-A-B-C, T120-A-B-C, T140-A-B-C, T160-A-B-C, T180-A-B-C, G80-A-B-C, G95-A-B-C, G125-A-B-C, R39-A-B-C, R50-A-B-C, R63-A-B-C, TC50A-A-B, TC50B-A-B, T75-A-B, TY-8-A-B, C37-A-3CCT-C, G45-A-3CCT-C, R80-A-B-C, PAR20-A-B-C, PAR30-A-B-C, PAR38-A-B-C, GX53-Sensor-A-B, GX53-A-B, MB-Sensor-Oval-A-B, MB-Sensor-Round-A-B, MB-Oval-A-B, MB-Round-A-B, A60-Sensor-A-B-C, A60-A-3CCT-C, A65-A-3CCT-C, A70-A-3CCT-C, BH115-A-B, BH135-A-B, BH150-A-B, BH175-A-B, BH195-A-B, BH160X85-A-B, BH195X95-A-B, GU10 lens-A-3CCT, GU10-A-3CCT, GU5 .3-A-3CCT, GU5 .3-Lens-A-B, TC50C-A-3CCT, TC50CA-B, T75-A-B, GX53-A-3CCT, TF(Y)-2 .5-A-B, TF(Y)-4-A-B, TF(Y)-6-A-B, TF(Y)-8-A-B, TF(Y)-10-A-B, TF(Y)-4M-A-B, TF(Y)-6M-A-B, TF(Y)-8M-A-B, GX70-A-B, GX70-A-3CCT, Downlight TD-2 .5B-A-3CCT, Downlight TD-4B-A-3CCT, Downlight TD-4 .5B-A-3CCT, Downlight TD-5B-A-3CCT, Downlight TD-6B-A-3CCT, Downlight TD-8B-A-3CCT, Spotlight HC2-2 .5B-A-3CCT, Spotlight HC2-3 .5B-A-3CCT, Spotlight HC2-5B-A-3CCT, Spotlight HC2-8B-A-3CCT, AR111-GU5 .3-A-B, AR111-GU10-A-B, HC2-2.5-A-B, HC2-3.5-A-B, TS21-2.5-A-B, TS22-2.5-A-B, GU10-Lens-3CCT, TS22BM-3CCT-A, TS5-2 .5-Lens-A-B, TS5-3 .5-Lens-A-B, TS-10-2 .5F-Lens-A-B, TS10-3 .5F-Lens-A-B, TS10-3 .5-Lens-A-B, HC2-5-A-B, HC2-8-A-B, TS22M-A-B

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.

NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

Test Result(s)：

1. EU RoHS Directive 2011/65/EU Annex II and amending Directive (EU) 2015/863 substance content

1.1 SCREENING BY X-RAY FLUORESCENCE SPECTROSCOPY AND CONFIRMED BY WET CHEMICAL METHOD OF LEAD, CADMIUM, MERCURY, CHROMIUM AND BROMINATED FLAME RETARDANTS (PBB & PBDE)

TESTED MATERIAL	SCHEME	TARGET RoHS SUBSTANCES	TEST METHOD USED	XRF RESULT (in mg/kg)	CHEMICAL TEST RESULT (in mg/kg)
001	001	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
002	002	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
003	003	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
004	004	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.A.	
005	005	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.A.	
006	006	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

TESTED MATERIAL	SCHEME	TARGET RoHS SUBSTANCES	TEST METHOD USED	XRF RESULT (in mg/kg)	CHEMICAL TEST RESULT (in mg/kg)
007	007	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
008	008	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.A.	
009	009	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
010	010	All	XRF + Chemical	Cd: N.D	Cr^{6+}: N.D (<5.0)
				Cr: Inconclusive	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
011	011	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
012	012	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

TESTED MATERIAL	SCHEME	TARGET RoHS SUBSTANCES	TEST METHOD USED	XRF RESULT (in mg/kg)	CHEMICAL TEST RESULT (in mg/kg)
013	013	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.A.	
014	014	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.A.	
015	015	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
016	016	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
017	017	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
018	018	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.A.	

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

TESTED MATERIAL	SCHEME	TARGET RoHS SUBSTANCES	TEST METHOD USED	XRF RESULT (in mg/kg)	CHEMICAL TEST RESULT (in mg/kg)
019	019	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
020	020	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
021	021	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
022	022	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.A.	
023	023	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
024	024	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

TESTED MATERIAL	SCHEME	TARGET RoHS SUBSTANCES	TEST METHOD USED	XRF RESULT (in mg/kg)	CHEMICAL TEST RESULT (in mg/kg)
025	025	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.D	
026	026	All	XRF	Cd: N.D	N/T
				Cr: N.D	
				Pb: N.D	
				Hg: N.D	
				Br: N.A.	

Remark(s):

- RL = Reporting Limits
- N.D = Not Detected (<RL)
- Detected = below the lower screening limit of table (a) and pass
- Mg/kg = parts per million = ppm
- N/T = Not tested
- N.A.= Not applicable

-The result of component (008) is the result of the retest supplement sample.

1.2 Total Phthalates Content

Test Method: IEC 62321-8: 2017

Analyte	CAS No.	Requirement (Max.), %	Reporting Limit, %	Sample, %
				001+002+003+011+012+015
Dibutyl Phthalate, DBP	84-74-2	0.1	0.005	<0.005
Benzyl Butyl Phthalate, BBP	85-68-7	0.1	0.005	<0.005
Diethylhexyl Phthalate, DEHP	117-81-7	0.1	0.005	<0.005
Diisobutyl Phthalate, DIBP	84-69-5	0.1	0.005	<0.005
Rating				PASS

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.

NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

Analyte	CAS No.	Requirement (Max.), %	Reporting Limit, %	Sample, %
				016+017+023+024+025
Dibutyl Phthalate, DBP	84-74-2	0.1	0.005	<0.005
Benzyl Butyl Phthalate, BBP	85-68-7	0.1	0.005	<0.005
Diethylhexyl Phthalate, DEHP	117-81-7	0.1	0.005	<0.005
Diisobutyl Phthalate, DIBP	84-69-5	0.1	0.005	<0.005
Rating				PASS

Analyte	CAS No.	Requirement (Max.), %	Reporting Limit, %	Sample, %
				019+020+021
Dibutyl Phthalate, DBP	84-74-2	0.1	0.005	<0.005
Benzyl Butyl Phthalate, BBP	85-68-7	0.1	0.005	<0.005
Diethylhexyl Phthalate, DEHP	117-81-7	0.1	0.005	<0.005
Diisobutyl Phthalate, DIBP	84-69-5	0.1	0.005	<0.005
Rating				PASS

Remark(s):

-All concentrations expressed in percentage (%)

-"<" means less than

-Method for determination of Phthalates are determined by Gas Chromatography Mass Selective Detector (GC-MSD)

-The test results only apply to the items tested.

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.

NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

TEST METHODS:

(1) Sample prepared with reference to IEC 62321-2 Ed1.0:2021 Determination of certain substances in electrotechnical products – Part 2: Disassembly, disjunction and mechanical sample preparation;

(2) Sample Screening testing with reference to IEC 62321-3-1 Ed1.0:2013 Determination of certain substances in electrotechnical products – Part 3-1: Screening – Lead, mercury, Cadmium, total chromium and total bromine using X-ray fluorescence spectrometry;

(a) It is the result on total Br while test item on restricted substances is PBBs/PBDEs. It is the result on total Cr while test item on restricted substances is Cr^{6+}.

(b) Results are obtained by XRF for primary screening, and further chemical testing by ICP-OES(for Cd, Pb, Hg), UV-Vis(for Cr^{6+}) and GC/MS(for PBBs, PBDEs) is recommended to be performed.

XRF screening limits in mg/kg for regulated elements according to IEC 62321-3-1 Ed1.0:2013

ELEMENT	POLYMER	METALS	COMPOSITE MATERIAL
Cd	BL≤(70-3σ) <X<(130+3σ) ≤OL	BL≤(70-3σ) <X<(130+3σ) ≤OL	LOD < X < (150+3σ)≤ OL
Pb	BL≤(700-3σ) <X<(1300+3σ) ≤OL	BL≤(700-3σ) <X<(1300+3σ) ≤OL	BL≤(500-3σ) <X<(1500+3σ) ≤OL
Hg	BL≤(700-3σ) <X<(1300+3σ) ≤OL	BL≤(700-3σ) <X<(1300+3σ) ≤OL	BL≤(500-3σ) <X<(1500+3σ) ≤OL
Cr	BL≤(700-3σ) <X	BL≤(700-3σ) <X	BL≤(500-3σ) <X
Br	BL≤(300-3σ) <X	--	BL≤(250-3σ) <X

Remark(s):

BL = Below Limit, OL = Over Limit, LOD = Limit of Detection, -- = Not Regulated

The XRF screening test for RoHS elements – The reading may be different to the actual content in the sample be of non-uniformity composition.

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.

NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

TEST METHODS:

(3) Wet Chemical Test Method


TESTING ITEM	CHEMICAL TESTING METHOD	RL	LIMIT
Cd	With reference to IEC 62321-5 Ed1.0:2013, by acid digestion and determined by ICP-OES	5.0mg/kg	100mg/kg
Pb	With reference to IEC 62321-5 Ed1.0:2013, by acid digestion and determined by ICP-OES	5.0mg/kg	1000mg/kg
Hg	With reference to IEC 62321-4 Ed1.1:2017, by acid digestion and determined by ICP-OES	5.0mg/kg	1000mg/kg
Cr^{6+} (for non-metal)	With reference to IEC 62321-7-2 Ed1.0:2017, by the colorimetric method	5.0mg/kg	1000mg/kg
Cr^{6+} (for metal)	With reference to IEC 62321-7-1 Ed1.0:2015 by the water-boiling method	/	/
PBBs Content	With reference to IEC 62321-6 Ed1.0:2015, by solvent extraction and determined by GC-MSD	5.0mg/kg	1000mg/kg
PBDEs Content	With reference to IEC 62321-6 Ed1.0:2015, by solvent extraction and determined by GC-MSD	5.0mg/kg	1000mg/kg
DEHP,BBP,DBP, DIBP	With reference to IEC 62321-8 Ed1.0:2017 clause 8.2.1.4 by gas chromatography-mass spectrometry	50mg/kg	1000mg/kg

Remark(s): According to IEC 62321-7-1 Ed1.0:2015, result on Cr^{6+} for metal sample is shown as Positive/Negative.


Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

TEST PROCESS

1. Test for Lead (Pb), Cadmium (Cd) contents(IEC 62321-5 Ed1.0:2013):




2. Test for Mercury (Hg) contents (IEC 62321-4 Ed1.1:2017):




3. Test for Nonmetallic Materials Chromium(Cr(VI)) contents (IEC 62321-7-2 Ed1.0:2017):

3.1 ABS/PC/PVC




Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China


3.2 others



4. Test for metal Chromium(Cr(VI)) contents (IEC 62321-7-1 Ed1.0:2015):




5. Test for PBBs & PBDEs contents (IEC 62321-6 Ed1.0:2015):




Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

6. Test for Phthalate content (DEHP,BBP,DBP,DIBP) (IEC 62321-8 Ed1.0:2017):

6.1 Test for general polymer



6.2 Test for THF soluble polymer



Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report

Sample description:


(001) White plastic shell
(002) Transparent plastic cover
(003) Grey white plastic frame
(004) Silver metal cover
(005) Silver metal screw
(006) Black electronic components (chip resistors)
(007) Black electronic components (ICs)
(008) Soldering
(009) Yellow electronic components (LED)
(010) Gray electronic components (color ring resistors)
(011) White plastic casing (electrolytic capacitor)
(012) Black plastic switch
(013) Silver connected to white metal light board
(014) Silver metal casing (electrolytic capacitor)
(015) Brown wet paper (electrolytic capacitor)
(016) Black plastic base (electrolytic capacitor)
(017) White plastic cover
(018) Silver metal spring buckle
(019) White plastic wire jacket
(020) Brown plastic wire jacket
(021) Blue plastic wire jacket
(022) Copper colored metal wire
(023) White plastic pin
(024) Translucent white plastic light bulb
(025) White plastic shell (bulb)
(026) Silver metal base (bulb)


Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Photo(s) of test sample(s):




(Whole product)








Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China


Test Report

















Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China

Test Report







********** End of Report **********

Unless otherwise stated, this test report is only responsible for the sample(s). This test report cannot be reproduced in partly without prior written permission of the testing Lab. Any inquiry about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accepted.
NAP Testing Technology Service (Zhongshan) Co., LTD
TEL：0760-86519632 E-mail:service@nap-testing.com
Add：4th floor Zone A and 5th floor, Site no. 81, Lixi Avenue, Banfu Borough, Zhongshan City, Guangdong Province, China